

- **GLASS—HEATED BACKLITE INOPERATIVE—TERMINAL SEPARATES FROM GLASS OR GRID BREAKS**
- **HEATED BACKLITE—INOPERATIVE—TERMINAL SEPARATES FROM GLASS OR GRID BREAKS**

**Article No.
93-26-1**

FORD: 1985-86 LTD
1985-94 CROWN VICTORIA, ESCORT, MUSTANG, TEMPO, THUNDERBIRD
1986-94 TAURUS
1988-93 FESTIVA
1989-94 PROBE

LINCOLN-MERCURY: 1985-86 CAPRI, MARQUIS
1985-87 LYNX
1985-92 MARK VII
1985-94 CONTINENTAL, COUGAR, GRAND MARQUIS, TOPAZ,
TOWN CAR
1986-94 SABLE
1987-89 TRACER
1991-94 TRACER
1993-94 MARK VIII

MERKUR: 1985-89 XR4TI
1988-89 SCORPIO

LIGHT TRUCK: 1985-90 BRONCO II
1985-94 BRONCO
1986-94 AEROSTAR
1991-94 EXPLORER
1993-94 VILLAGER

This TSB article is being republished in its entirety to include 1992-94 vehicles with heated backlites.

ISSUE: An inoperative electric rear window defroster (heated backlite) may be caused by bond separation of the pigtail terminal to bus bar or broken grid lines.

ACTION: Use a rear window defroster service kit to repair pigtail connections, Figure 1 and grid line breaks, Figure 2.

The Service Kit is available from:

Marketing East Company

#10 Liberty Street

North Andover, Massachusetts 01845

Telephone: (508) 689-9565

This Service kit consists of five individual window kits which contain the following pieces.

- One epoxy adhesive bi-pack
- One application stick
- One grid line mask
- One set of application instructions

To order this Service Kit, fill out and mail the order form provided, Figure 3.

OTHER APPLICABLE ARTICLES: NONE


SUPERSEDES: 91-5-1

WARRANTY STATUS: INFORMATION ONLY


OASIS CODES: 102000, 205000

TERMINAL REPAIR


1. PROBLEM




2. APPLY CONDUCTIVE CEMENT



3. PEEL OFF MASK/APPLY HEAT



4. SOLUTION




TB-8375-B


Figure 1 - Article 93-26-1

GRID REPAIR


1. PROBLEM




2. APPLY CONDUCTIVE CEMENT



3. APPLY HEAT



4. SOLUTION



TB-8376-B

Figure 2 - Article 93-26-1

QUANTITY _____ Service Kit(s) x \$43.00 = _____ Total

Part Order Number: 50-25-0584-0029

Dealership: _____

Street Address: _____

City-State-Zip: _____

Attention Parts Manager: _____

Order form will be forwarded with initial purchase.

Parts price includes Postage and Handling.

Mail with check or money order to:

MARKETING EAST COMPANY
#10 Liberty Street
North Andover, MA 01845
Attn: Sales
Phone: (508) 689-9565

QUANTITY _____ Service Kit(s) x \$43.00 = _____ Total

Part Order Number: 50-25-0584-0029

Dealership: _____

Street Address: _____

City-State-Zip: _____

Attention Parts Manager: _____

Order form will be forwarded with initial purchase.

Parts price includes Postage and Handling.

Mail with check or money order to:

MARKETING EAST COMPANY
#10 Liberty Street
North Andover, MA 01845
Attn: Sales
Phone: (508) 689-9565

TB-1420-B