

**BALL JOINT—REPLACEMENT PROCEDURE—
SERVICE TIP**

**Article No.
95-14-4**

FORD: 1980-1995 CROWN VICTORIA, MUSTANG

LINCOLN: 1980-1995 TOWN CAR

MERCURY: 1980-1995 GRAND MARQUIS

ISSUE

Serviceability cost can be lowered for the customer if a worn lower ball joint is replaced separately, rather than as a lower arm and ball joint assembly.

ACTION

Replace the lower ball joint with the individual service replacement ball joint. Refer to the 1995 Mustang Service Manual, Page 04-01-9 for service details.

NOTE

IT IS NOT NECESSARY TO REPLACE THE LOWER CONTROL ARM WHEN REPLACING THE BALL JOINT.

PART NUMBER	PART NAME
F4ZZ-3050-A	Ball Joint (1994-95 Mustang, 1995 Town Car, Grand Marquis And Crown Victoria)
F2ZZ-3050-A	Ball Joint (All Others)

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: INFORMATION ONLY

OASIS CODES: 303000, 304000