WINDSHIELD AND INTERIOR GLASS—FOG/FILM

Article No. 96-22-1

FORD: 1984-1986 LTD

1984-1988 EXP 1984-1994 TEMPO

1984-1997 CROWN VICTORIA, ESCORT, MUSTANG, THUNDERBIRD

1986-1997 TAURUS 1988-1993 FESTIVA 1989-1997 PROBE 1994-1997 ASPIRE 1995-1997 CONTOUR

1984-1997 F-150-350 SERIES

1986-1990 BRONCO II 1986-1996 BRONCO

1986-1997 AEROSTAR, ECONOLINE, RANGER

1988-1997 F SUPER DUTY 1991-1997 EXPLORER 1995-1997 WINDSTAR

LINCOLN: 1984-1992 MARK VII

1984-1997 CONTINENTAL, TOWN CAR

1993-1997 MARK VIII

MERCURY: 1984-1986 MARQUIS

1984-1987 LN7, LYNX 1984-1994 TOPAZ

1984-1997 COUGAR, GRAND MARQUIS

1986-1997 SABLE 1987-1989 TRACER 1991-1994 CAPRI 1991-1997 TRACER 1995-1997 MYSTIQUE 1993-1997 VILLAGER

MERKUR: 1985-1989 XR4TI

1988-1990 SCORPIO

This TSB article is being republished in its entirety to update the model years.

ISSUE

Customers with concerns of glass fogging (film) and with the chemicals that cause this fog can be advised that Ford Motor Company has extensively tested this material and found that it is <u>not</u> a health hazard. The film is caused by some of the chemicals used during the manufacture of the interior trim.

ACTION

At the present time, there is no known field fix to prevent the window fogging, however, glass cleaner such as Ford Glass Cleaner (E4AZ-19C507-AA) has been found to be the best for film removal.

PART NUMBER	PART NAME
E4AZ-19C507-AA	Ford Glass Cleaner

Article No. 96-22-1 Cont'd.

OTHER APPLICABLE ARTICLES: NONE

SUPERSEDES: 86-13-6

WARRANTY STATUS: INFORMATION ONLY

OASIS CODES: 102000, 107000